

VE7RXZ Issue

VE7RXZ is experiencing an issue where it is transmitting a constant tone. The tone is being transmitted without the usual 100.0Hz tone that the repeater usually does. If you have CTCSS enabled on your radio, you would need to turn this off to hear the tone.

We are in communications with Island Communications who host the repeater to try to resolve this issue.